

ASSEMBLY VIEW






Assembly Instructions

1) Slide the ferrule onto the cable and strip the cable to the dimensions as shown, taking care not to nick the centre conductor or braid.



2) Slide the insulator over the centre core and then solder the pin onto the centre core. Slide the pin into the body until fully located ensuring that the cable braid is on the outside of the connector mandril.

3) Slide the ferrule forward and crimp.




Crimp Hex. Sizes:

3.25mm Hex, Solder Centre Core

Strip Dimensions:

A=5.35mm, B=0.00mm, C=4.70mm



	Description	Material	Finish
1	Body	Brass	Nickel
2	Contact	Brass	Gold
3	Dielectric	PTFE	White
4	Ferrule	Brass	Nickel
5	O-Ring	Rubber	Red
6	Pin	Brass	Gold
7	Insulator	PTFE	White
8	Lock Nut	Brass	Nickel
9	Washer	Brass	Nickel

Unless otherwise specified tolerances $0.5-5=\pm0.2$ $>5-30=\pm0.4$ $>30-120=\pm0.6$ $>120-315=\pm1.0$ $>315-1000=\pm1.6$ Angles $=\pm5^{\circ}$ Units = mm

This document is the confidential property of Gigatronix Limited and may not be copied, reproduced or transmitted to any third party without written authorisation.



Author	РЈР
Drawn by	PJP
Drawing date	07/09/2020
Checked by	DB
Checked date	07/09/2020
Scale	Not to scale

Part Number

NT02-3161-C06WP

Title: N Type Waterproof Crimp Bulkhead Jack, IP68, Nickel Plated, RG174, LBC100, RG316